

Billingshurst Parish Council

*St Mary's Church
Grave Details Class 2,
Action Within 6 Months*

SECTION: A

Grave Section	A	Grave No	007
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Florence	First Name 2	
Surname1	Allwright	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	high movement noted		

Grave Section	A	Grave No	045
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Elizabeth	First Name 2	
Surname1	Farmer	Surname 2	
Death1	29/12/1967	Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone/base loose passed test		

Grave Section	A	Grave No	061
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Iris	First Name 2	
Surname1	Sayers	Surname 2	
Death1	15/05/1987	Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone loose passed test, vase		

Grave Section	A	Grave No	072
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Ernie	First Name 2	
Surname1	Baylie	Surname 2	
Death1	09/08/1988	Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	base/foundation loose passed test, home made kerbs		

Grave Section	A	Grave No	090
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Wilfred	First Name 2	Louisa
Surname1	Cooper	Surname 2	Cooper
Death1	16/01/1988	Death 2	09/06/1995
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	headstone/base movement noted, hole in front of grave		

Grave Section	A	Grave No	125
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Charles	First Name 2	
Surname1	Farhall	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	ivy on top, open joints, steps split/out of line/loose		

SECTION: B

Grave Section	B	Grave No	005
Grave Condition	2	Inspection Date:	15/09/2009
First Name 1	Thomas	First Name 2	Thomas
Surname1	Carter	Surname 2	Carter
Death1	26/06/1880	Death 2	02/04/1858
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	kerb loose full grave top split statue on base full grave top piece of stone on grave base projects on to path - brick foundation loose/missing		

Grave Section	B	Grave No	039
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Jane	First Name 2	Rebecca
Surname1	Merrikin	Surname 2	Merrikin
Death1	14/02/1960	Death 2	23/12/1923
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	corners loose metal post/chain in grave		

Grave Section	B	Grave No	046
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	unable to inspect due to being covered in ivy		

Grave Section	B	Grave No	076
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	6
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	corner loose, side out of location covered in ivy with ivy in joints		

Grave Section	B	Grave No	103
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	side/corner already laid exposing centre, ivy, centre brick supports on another grave		
Grave Section	B	Grave No	104
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Abel	First Name 2	
Surname1	Lefford	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	7	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	>1m headstone
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	bricks piled on grave ivy		
Grave Section	B	Grave No	124
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Sarah	First Name 2	
Surname1	Smart	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	9
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	side/corner out of line/leaning, kerbs split, covered in ivy, ivy in joints		
Grave Section	B	Grave No	125
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	12
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	high angles, side out of line, covered in ivy, ivy in joints		

Grave Section	B	Grave No	127
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	corner loose, ivy in joints, foundation exposed/out of line		

Grave Section	B	Grave No	232
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Frances	First Name 2	
Surname1	Penfold	Surname 2	
Death1	28/10/1919	Death 2	
Front/Rear Pitch:		Side Pitch:	5
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	base/foundation passed 35kg		

Grave Section	B	Grave No	235
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	kerbs loose in grave		

SECTION: C

Grave Section	C	Grave No	001
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Evelyn	First Name 2	Frederick
Surname1	Dudman	Surname 2	Dudman
Death1	01/10/1978	Death 2	29/10/1982
Front/Rear Pitch:	4	Side Pitch:	7
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone/base loose		

Grave Section	C	Grave No	002
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	James	First Name 2	
Surname1	Botting	Surname 2	
Death1	04/09/1969	Death 2	
Front/Rear Pitch:	6	Side Pitch:	12
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	foundation movement, high angles		

Grave Section	C	Grave No	010
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	George	First Name 2	Ethel
Surname1	Redman	Surname 2	Redman
Death1	08/12/1964	Death 2	03/04/1965
Front/Rear Pitch:	11	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	high angles, foundation movement		

Grave Section	C	Grave No	011
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Walter	First Name 2	Marjory
Surname1	Denman	Surname 2	Denman
Death1	13/02/1963	Death 2	14/06/1969
Front/Rear Pitch:	5	Side Pitch:	9
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone/base loose		

Grave Section	C	Grave No	016
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Richard	First Name 2	
Surname1	Burrough	Surname 2	
Death1	12/03/1958	Death 2	
Front/Rear Pitch:	6	Side Pitch:	7
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	base/foundation movement		
Grave Section	C	Grave No	020
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Frederick	First Name 2	
Surname1	Humphrey	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	support/book part buried		
Grave Section	C	Grave No	042
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	support/base		
Grave Section	C	Grave No	068
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	Mary	First Name 2	William
Surname1	Evershed	Surname 2	Evershed
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	9
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	book/support loose part buried		

Grave Section	C	Grave No	073
Grave Condition	2	Inspection Date:	16/09/2009
First Name 1	George	First Name 2	
Surname1	Linfield	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	~ No action taken	Stone Mason:	Unknown
Comments:	support/base loose		
Grave Section	C	Grave No	102
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Ada	First Name 2	Robert
Surname1	Crisp	Surname 2	Crisp
Death1		Death 2	
Front/Rear Pitch:	4	Side Pitch:	9
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	~ No action taken	Stone Mason:	Unknown
Comments:	headstone/base		
Grave Section	C	Grave No	121
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Florence	First Name 2	Charles
Surname1	Wood	Surname 2	Wood
Death1	22/05/1950	Death 2	20/02/1955
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	~ No action taken	Stone Mason:	Unknown
Comments:	kerb/corner loose, stump		
Grave Section	C	Grave No	135
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Florence	First Name 2	Maurice
Surname1	Randall	Surname 2	Randall
Death1		Death 2	
Front/Rear Pitch:	6	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	~ No action taken	Stone Mason:	Unknown
Comments:	headstone/base, foundation		

Grave Section	C	Grave No	141
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Sydney	First Name 2	Ivy
Surname1	Thompson	Surname 2	Thompson
Death1	01/05/1969	Death 2	23/04/2000
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	>1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone/base, vase		
Grave Section	C	Grave No	177
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Sarah	First Name 2	Ernest
Surname1	Smith	Surname 2	Smith
Death1	19/09/1965	Death 2	29/05/1969
Front/Rear Pitch:	7	Side Pitch:	4
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone/base movement		
Grave Section	C	Grave No	185
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	James	First Name 2	
Surname1	Burdfield	Surname 2	
Death1	24/03/1935	Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone & Kerbs
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	headstone/base high movement		
Grave Section	C	Grave No	232
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	book/support loose high movement, part buried		

Grave Section	C	Grave No	246
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Emma	First Name 2	George
Surname1	Hampshire	Surname 2	Hampshire
Death1	12/04/1941	Death 2	23/09/1944
Front/Rear Pitch:	9	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	foundation movement noted		
Grave Section	C	Grave No	253
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	William	First Name 2	
Surname1	Brickett	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	support/base loose		
Grave Section	C	Grave No	268
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Antony	First Name 2	
Surname1	Sims	Surname 2	
Death1	30/03/1936	Death 2	
Front/Rear Pitch:	0	Side Pitch:	9
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	<1m headstone & Kerbs
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	bird bath support/base loose		
Grave Section	C	Grave No	320
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Maria	First Name 2	Giles
Surname1	Gray	Surname 2	Gray
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	book/base, vase, home made kerbs		

SECTION: D

Grave Section	D	Grave No	017
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Richard	First Name 2	
Surname1	Hunt	Surname 2	
Death1	19/08/1903	Death 2	
Front/Rear Pitch:	4	Side Pitch:	4
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Cross
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	1st base/foundation movement at 35kg, 1st base split at bottom		

Grave Section	D	Grave No	022
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	top out of line, gap under top, kerb damaged, full grave top		

Grave Section	D	Grave No	024
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Maurice	First Name 2	Eliza
Surname1	Ireland	Surname 2	Ireland
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	kerb loose, kerb already laid, top out of line, full grave top		

Grave Section	D	Grave No	029
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	A	First Name 2	
Surname1	Spinks	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Cross
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	cross already split/missing, 1/2 base		

Grave Section	D	Grave No	051
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Kathleen	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Cross
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	cross already missing, 2/3 base loose		
Grave Section	D	Grave No	052
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Anthony	First Name 2	
Surname1	Innes	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Cross
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	cross already missing, bases loose		
Grave Section	D	Grave No	093
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Misc
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	parts of cross, metal memorials under tree		
Grave Section	D	Grave No	114
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Caroline	First Name 2	
Surname1	Tullett	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^ No action taken	Stone Mason:	Unknown
Comments:	support/base loose		

Grave Section	D	Grave No	124
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Ellen	First Name 2	
Surname1	Laker	Surname 2	
Death1	18/01/1941	Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Book
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	book movement noted part buried		

Grave Section	D	Grave No	133
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Robert	First Name 2	Lucy
Surname1	Myram	Surname 2	Myram
Death1		Death 2	11/04/1925
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	>1m headstone
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	memorial split in half and been repaired required monitoring		

Grave Section	D	Grave No	136
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	>1m Headstone, Kerbs
Action Taken:	^No action taken	Stone Mason:	Unknown
Comments:	unable to inspect due to ivy, passed 35kg		

SECTION: E

Grave Section	E	Grave No	010
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	A	First Name 2	M
Surname1	Lane	Surname 2	Lane
Death1		Death 2	12/03/1808
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	side/corners been (poorly) repaired but loose, ivy in joints, sides not secured to top		

Grave Section	E	Grave No	016
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Unknown	First Name 2	
Surname1		Surname 2	
Death1		Death 2	
Front/Rear Pitch:	5	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	>1m headstone
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	movement, top of memorial missing exposing internal metal frame work, top part of memorial splitting/cracked on rear		

Grave Section	E	Grave No	033
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Frances	First Name 2	
Surname1	Evershed	Surname 2	
Death1	28/11/1866	Death 2	
Front/Rear Pitch:	0	Side Pitch:	0
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Kerbs
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	kerb loose, full grave top, top out of line		

Grave Section	E	Grave No	037
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Mary	First Name 2	John
Surname1	Greenfield	Surname 2	Greenfield
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	4
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	~No action taken	Stone Mason:	Unknown
Comments:	top split, side/corner loose, ivy, kerb split, sides out of line, piece of stone leaning on corner		

Grave Section	E	Grave No	039
Grave Condition	2	Inspection Date:	17/09/2009
First Name 1	Thomas	First Name 2	
Surname1	Greenfield	Surname 2	
Death1		Death 2	
Front/Rear Pitch:	0	Side Pitch:	7
Recomendations:	Safe, Requires Repair within 6 Month	Grave Type:	Tomb
Action Taken:	No action taken	Stone Mason:	Unknown
Comments:	corner/end split, top out of line, dead ivy in joints, sapling next to memorial		